

Vacuum Pressure Gauge

■ Product description

Vacuum Pressure Gauge's measure range is from 0 to -0.1MPa.

It can be used at a fixed station in the vacuum distribution network, or as a control device with a quick release connection to the vacuum intakes of bags or membranes.

It enables the vacuum rate to be measured at any point in the network and therefore allows possible leaks to be detected. it is the essential tool for the operator during composite production in a vacuum

■ PHYSICAL PREPERTIES

Measure Range	0 to -0.1MPa/14.5psi
Diameter	60mm&100mm
Fitting	M14*1.5/ M20*1.5
Using Temperature	-25℃ +60℃
Relative humidity	≤ 85%
Oscillation frequency	<25HZ
Amplitude	≤ 1mm

■ Notes

Should be regularly tested (at least once every three months)

No shelf life limitation.

No skin irritaion problems experienced.

